



Fig. 1


VG4160  
Configuration  
Drawing



09766932.012201




# VG4000<sup>+</sup> Block Diagram



VG 4000<sup>+</sup> ARCHITECTURE

Fig. 2





# System Controller I/O Card






Fig. 4




# Quad OC3 Block Diagram



60 →

Fig. 5



# VLC - VDSL Line Card







Fig. 6



# ViaJet A40x Block Diagram





# ViaWay A406




Fig. 7b





# Typical Digital Set-Top Box




Fig. 7C

802

806




008



8/0

8/2



# Node Management Paths





Fig. 9





FOIA b 7 - D

# Connection Management





Fig. 11



# CATV/Broadcast Management




Fig. 12

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☒ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**